




OECD Conference on Environmental Justice

28-29 May 2024

OECD Headquarters, Paris



Conférence de l'OCDE sur la justice environnementale

28-29 mai 2024

Siège de l'OCDE, Paris

Unpacking inequitable distribution of environmental hazards and amenities
Fiona Macleod CEng FIChemE

BHOPAL – A Case Study



The world's worst industrial accident

What went wrong?

accident prevention, preparedness, response and follow up



Former UCIL Bhopal factory today

Photo taken August 2023 – @thechemicaldetective www.thechemicaldetective.blog

Bhopal UCIL Tragedy

When?

Just after midnight on the night of 2/3 December 1984

Where?

Union Carbide India Limited (UCIL) factory in Bhopal, India

What?

Toxic gas was released into the community

How?

Water mixed with chemicals leading to a runaway reaction

Who?

**Thousands died and hundreds of thousands were injured
The legacy continues to blight the lives of local people today**

Why? – Contributing Causes

Operational decisions in the 1980s – running to closure

- Increased inventory
- Loss of experienced staff
- Operational workarounds
- Reduced maintenance
- Compromised safety systems

Why? – Root Cause

Design decisions made in the 1970s – Inherent Safety

- Process Hazard Analysis
- Materials of Construction
- Equipment Reliability

Bhopal Gas Tragedy

02/03 December 1984
Bhopal, Madhya Pradesh, India

UNION CARBIDE

02 December
9.30 p.m.

10.30 p.m.
• Water escapes into main process pipe system, and essentially MIC storage tank E-610.
• Chemical reaction between MIC and water begins.

11.00 p.m.
• MIC storage tank pressure rises to 1.7 bar, which is still within safe operating limits of 1.1 bar to 2.7 bar..

03 December
12.15 a.m.

• MIC storage tank pressure rises rapidly from 3.1 bar to 4.8 bar.
• Operator senses heat radiating and rumbling noises from tank.
• Supervisor starts Vent Gas Scrubber (VGS) circulation pumps.

12.25 a.m.

• Chemical reaction between MIC and water becomes uncontrolled..
• MIC gas starts escaping from VGS stack.

12.45 a.m.

BHOPAL GAS TRAGEDY

2 - 3 December 1984
Bhopal, Madhya Pradesh, India.

IChemE ADVANCING CHEMICAL ENGINEERING WORLDWIDE

HAZARD ASSESSMENT NOT HIGHLIGHTED BY:

1. UCIL
2. LOCAL AUTHORITY

Feasibility and safety levels of UCIL plant not evaluated

Allocation of UCIL plant close to densely populated settlements Due to economic advantages

Unrestricted large scale manufacturing and storage of pesticide

MINIMISE

- Use small quantities of hazardous substances
- Reduction of MIC intermediate inventory
- MIC is not essential as a raw material nor a product.

INHERENTLY SAFER DESIGN
REPLACE SOURCE OF HAZARD

SUBSTITUTE

Replace hazardous reaction with one of less hazard

- Use a safer process route. Avoid MIC formation. React alphanaphthol and phosgene to produce chloroformate ester, followed by reaction with methylamine to yield carbaryl

SIMPLIFY

- Eliminate unnecessary complexity to reduce risk of human error
- Design equipment to totally contain MIC at ambient temperature or the maximum attainable process temperature.

Identify, evaluate and control hazards involved in a process.
Should address:

1. Process hazards
2. Engineering and administrative controls
3. Consequences of deviation
4. Steps required to correct or avoid deviation.

During leakage After leakage

Three main components:

- Prevention
- Internal and external communication
- Mitigation

UCIL FAILED TO DELIVER AN EFFECTIVE ERP.

UNDER-DIMENSIONING OF SAFETY FEATURES

Vent gas scrubber could not handle the large influx of MIC even if it were in operation.

ASSET INTEGRITY AND RELIABILITY

1. The refrigeration system was not in use.
2. Tank temperature was not logged.
3. Operator thought the tank's pressure meter was unreliable.
4. Evacuation tank E-619 was not empty.
5. Corroding iron pipelines were used.
6. Vent gas scrubber was under maintenance.
7. Water curtains were not tall enough to mitigate the gas leak.

REDUCED EMPHASIS ON SAFETY

8. Concentration of chloroform in the tank was too high.
9. The tank was not pressurised due to a leaky valve.
10. The tank's high-temperature alarm was not functioning.
11. Flare tower was disconnected from the plant pipe system.
12. Many valves, vent lines, feed lines, etc. were in poor condition.

EMPLOYEE PARTICIPATION

- Period of safety training was reduced from 6 months to 15 days
- Neglecting of specific instructions
 - Failure to communicate
- Giving orders without comprehending the nature of task
 - Not taking efficient corrective measures
- Poor perception of risks severity
 - Manpower in safety and maintenance was reduced to save cost.

Regular Training and Performance Assessment of Employees

Education of Workers

- Shortened training from 6 months to 8 weeks
- Underqualified Methyl isocyanide (MIC) operators
- Plant operating manual is only available in English

Green Revolution

- Lacks enforceable international standards for environmental safety and industrial disaster preparedness.

False Information

1. Residents of adjacent bastis
2. City & State Authorities
3. Union Carbide India Limited

Staffing Policy

- Operates continued to plant despite severe 9 months, but never the result of misuse examinations
- Operators continued to plant despite severe 9 months, but never the result of misuse examinations

UCIL Cost Cutting Measures

- Positions of Maintenance Supervisor, Operating Shifts, Maintenance Shifts
- Demand for extra safety precautions led to warnings that appointments could be terminated
- Workers and operators routinely exposed to toxic chemicals

Early Warnings

- 1974 Residents found a well contaminated. Analyses of soil showed contamination with heavy metals.
- 1976 Two trade unions reacted to plant pollution issue. Letters went to plant manager, factory inspector, and Ministry of Labour of Madhya Pradesh.
- 1978 Factory caught in a big fire. Flammable materials were caught starting in cylinders other than those designated for purpose.
- 1981 Worker splashed with phosgene and died after 72 hours.
- 1982 January Phosgene leak February, August, October MIC leak (resulting in burns over body of victims)
- 1983-1984 Highlighting regularly leaks of MIC, chloroform, phosgene, isocyanide, phosgene, and carbon tetrachloride.

Content of Gas Cloud

Union Carbide has not released the information they have available.

Possible Components

- Methyl isocyanide
- Methylamine
- Monoisocyanuric acid
- Hydrogen cyanide
- Carbon monoxide
- Carbon dioxide
- Nitrogen oxides
- Ammonia
- Chloroform
- Hydrogen chloride
- Phosgene

Leading to Hypoxia and Asphyxia

Health Effect

- Ophthalmic
- Respiratory
- Immunological
- Neurological
- Neuro-muscular
- Cancers
- Gynecological

State of Safety System

on December 3, 1984

Under consideration of safety measures

Inefficient maintenance

Many valves, vent lines, feed lines etc. were in poor condition

The tank was not pressurised

Corrosion was present because of corrosion

The tank's high-temperature alarm was not functioning.

Tank E-610 (the evacuation tank) was not empty.

Modern monitoring tank E-610 sense slowly abnormal pressure. The reason might be a faulty meter or tank's inability to monitor pressure.

Line connecting VGS to tank lower was metered closed.

The tank was not pressurised

The tank's high-temperature alarm was not functioning.

Tank E-610 (the evacuation tank) was not empty.

Modern monitoring tank E-610 sense slowly abnormal pressure. The reason might be a faulty meter or tank's inability to monitor pressure.

Line connecting VGS to tank lower was metered closed.

Many valves, vent lines, feed lines etc. were in poor condition

The tank was not pressurised

Corrosion was present because of corrosion

The tank's high-temperature alarm was not functioning.

Tank E-610 (the evacuation tank) was not empty.

Modern monitoring tank E-610 sense slowly abnormal pressure. The reason might be a faulty meter or tank's inability to monitor pressure.

Line connecting VGS to tank lower was metered closed.

Many valves, vent lines, feed lines etc. were in poor condition

Education of Workers

- Shortened training from 6 months to 8 weeks
- Underqualified Methyl isocyanide (MIC) operators
- Plant operating manual is only available in English

Green Revolution

- Lacks enforceable international standards for environmental safety and industrial disaster preparedness.

False Information

1. Residents of adjacent bastis
2. City & State Authorities
3. Union Carbide India Limited

Staffing Policy

- Operates continued to plant despite severe 9 months, but never the result of misuse examinations
- Operators continued to plant despite severe 9 months, but never the result of misuse examinations

UCIL Cost Cutting Measures

- Positions of Maintenance Supervisor, Operating Shifts, Maintenance Shifts
- Demand for extra safety precautions led to warnings that appointments could be terminated
- Workers and operators routinely exposed to toxic chemicals

Bhopal Disaster

December 3, 1984

- 0 trained engineer on site.
- 3000 - 10000 died during the first week
- 100000 - 200000 have got permanent damage
- 520000+ exposed to the gases
- 200000+ were children

Early Warnings

- 1974 Residents found a well contaminated. Analyses of soil showed contamination with heavy metals.
- 1976 Two trade unions reacted to plant pollution issue. Letters went to plant manager, factory inspector, and Ministry of Labour of Madhya Pradesh.
- 1978 Factory caught in a big fire. Flammable materials were caught starting in cylinders other than those designated for purpose.
- 1981 Worker splashed with phosgene and died after 72 hours.
- 1982 January Phosgene leak February, August, October MIC leak (resulting in burns over body of victims)
- 1983-1984 Highlighting regularly leaks of MIC, chloroform, phosgene, isocyanide, phosgene, and carbon tetrachloride.



Content of Gas Cloud

Union Carbide has not released the information they have available.

- Possible Components**
- Methyl isocyanide
 - Methylamine
 - Monoisocyanuric acid
 - Hydrogen cyanide
 - Carbon monoxide
 - Carbon dioxide
 - Nitrogen oxides
 - Ammonia
 - Chloroform
 - Hydrogen chloride
 - Phosgene

Health Effect

- Ophthalmic
- Respiratory
- Immunological
- Neurological
- Neuro-muscular
- Cancers
- Gynecological

State of Safety System

on December 3, 1984

Under consideration of safety measures

Inefficient maintenance

Many valves, vent lines, feed lines etc. were in poor condition

The tank was not pressurised

Corrosion was present because of corrosion

The tank's high-temperature alarm was not functioning.

Tank E-610 (the evacuation tank) was not empty.

Modern monitoring tank E-610 sense slowly abnormal pressure. The reason might be a faulty meter or tank's inability to monitor pressure.

Line connecting VGS to tank lower was metered closed.

The tank was not pressurised

Corrosion was present because of corrosion


The tank's high-temperature alarm was not functioning.

Tank E-610 (the evacuation tank) was not empty.

Modern monitoring tank E-610 sense slowly abnormal pressure. The reason might be a faulty meter or tank's inability to monitor pressure.

Line connecting VGS to tank lower was metered closed.

Many valves, vent lines, feed lines etc. were in poor condition





OECD Guiding Principles for Chemical Accident Prevention, Preparedness and Response

**PREVENTING ... LOSS OF
CONTAINMENT OF
HAZARDOUS SUBSTANCES**

**PREPARING ...MITIGATING
ADVERSE EFFECTS OF
ACCIDENTS THROUGH
EMERGENCY PLANNING,
LAND-USE PLANNING, AND
COMMUNICATION WITH THE
PUBLIC**

**RESPONDING ... MINIMISE
THE ADVERSE
CONSEQUENCES...**

FOLLOW-UP ...CLEAN-UP ... ACCIDENT REPORTING AND INVESTIGATION

Guidance on Change of Ownership in Hazardous Facilities



Managing change

- Change of ownership
 - Closure
-

Preventing



Inventory
minimisation –
what you don't
have, can't leak



Materials of
construction –
inherent safety



Equipment
specification -
reliability



Instrumented
Safety Systems –
Independent
safeguards



Management of
Change



Process Hazard
Analysis and
Risk
Assessment

Preventing - Bhopal




Large Quantities of a Hazardous Intermediate (MIC) stored on a site in the middle of a town



Vent gas header constructed of Carbon Steel instead of Stainless Steel



MIC transfer and circulation pumps unreliable



Lack of instrumentation and Independent safeguards



Workarounds common No effective Management of Change



Loss of trained staff Lack of appreciation of hazards

Preparing


Emergency
planning

Land use
planning

Communication

Preparing - Bhopal

- Emergency planning
 - Flare disconnected
 - Vent gas scrubber not in operation
 - Refrigeration decommissioned
 - Water curtain pressure insufficient
 - Public alarm silenced
- Land use planning
 - Growth of communities around site
- Communication
 - Limited



Responding

Alert response personnel

Trigger the Emergency Plan

Warn the public

Limit adverse effects to health and environment

Effective and open communication with the public

Responding – Bhopal – Too little, too late

- Instrument alarms overridden
- Public alarm system was silenced
- Panicking public left their homes and fled into gas cloud
- Hospitals had no idea how to treat victims
- Compensation was too little and too late
- Health care wholly inappropriate
- Lease terminated before clean up
- Groundwater contamination continues

Follow up

The application of the **Polluter Pays Principle** acts as a major incentive for management of hazardous installations to do everything in their power to avoid accidents

Areas affected by accidents involving hazardous substances should be monitored to determine if there are any **long-term or delayed consequences of acute exposures**

Appropriate epidemiological and **medical follow-up** procedures should be put into place for monitoring and observation of persons exposed to hazardous substances

An **investigation** should be a fact-finding activity to learn from experience, not an exercise designed to allocate blame or liability.

Follow up - Bhopal

- Chemical plant equipment, piping and structures have been left to corrode and are in an increasingly dangerous state.
- There is no meaningful security - access to the wasteland is open to all, including children and grazing domestic animals.
- There are ~350 tonnes of packaged hazardous waste that need to be contained, stabilised and safely destroyed.
- The soil inside the is contaminated, and ground water pollution continues to spread.
- There has been no effective clean-up of the former UCIL site or the external Solar Evaporation Ponds in Bhopal.
- The surrounding communities continue to suffer.

The second tragedy - Environmental

- Environmental problems at the factory predate the 1984 accident
- A failure to maintain the solar evaporation pond barriers or control hazardous waste has led to heavy contamination of the groundwater in and around the abandoned factory with
 - Heavy metals including mercury, chromium and lead
 - Organochlorides classed as persistent organic pollutants
- Many of the communities affected have still not been provided with a reliable source of clean drinking water
- Domestic animals continue to graze on contaminated land inside and outside of the factory
- The ground water pollution continues to spread.

Final Message

Before construction

- Substitute
- Minimise
- Simplify
- Moderate

Build in Error tolerance

Inherent safety by design

After closure

Timely and effective clean-up




How to break the impasse?

- 1989 US\$470M settlement brokered by Government did not include funds for remediation
 - 1994 US parent company sold its majority share in Indian Subsidiary to fund a hospital
 - 1998 State Government cancelled the lease and resumed control of the site
 - 2013 Indian NGO outlines steps before environmental remediation can proceed
 - 2024 – No progress
-
- GOI – Government of India
 - Parent - UCC – Union Carbide Corporation
 - Subsidiary - UCIL – Union Carbide India Ltd
 - Buyer - Eveready – Eveready Industries India Ltd
 - MP – Madhya Pradesh State Government
 - NGO - CSI – Centre for Science and Environment, Delhi, India

ACTION PLAN ENVIRONMENTAL REMEDiation IN AND AROUND UCIL, BHOPAL

EXPERT ROUNDTABLE, APRIL 25-26, 2013



Summary of Action Plan

IMMEDIATE MEASURES	
SECURING THE SITE AND PREVENTING ANNUAL SURFACE WATER RUNOFF	THREE MONTHS
Fencing and guarding of the UCIL site and landfill area within the SEP	Immediate
Stopping construction at the SEP area	Immediate
Measures to be taken to protect annual surface water runoff from the site during monsoon	Three months
EXCAVATION, RECOVERY AND CHARACTERISATION OF WASTE DUMPED AT THE UCIL SITE	SIX MONTHS
Cleaning vegetation and dewatering the site	One month
Identification and refurbishment of a temporary storage area for excavated waste	Three months
Excavation and recovery of dump materials from already identified and new sites	Three months
Recovery of mercury present in drains, pan filters and soil with the help of local community	Three months
Characterisation and inventerisation of the collected waste for proper treatment and/or disposal	Six months
CHARACTERISATION AND INCINERATION OF THE STORED WASTE AT THE UCIL SITE	SIX MONTHS
Trial at the Pithampur incinerator with ten tonnes of similar waste from HIL, Kerala	Three months
Characterisation results of the stored UCIL waste to be made public; if required, further characterisation and inventerisation to be done in parallel with the trials	Three months
Waste with high calorific value and hazardous in nature to be incinerated with continuous stack monitoring; remaining waste to be dealt with suitable decontamination/remediation measures	Six months
MEDIUM- AND LONG-TERM MEASURES	
GROUNDWATER CONTAMINATION ASSESSMENT AND REMEDIATION OUTSIDE THE UCIL SITE	TWO TO THREE YEARS
Field investigation and lab analysis of the groundwater	One year
Possibility of hydraulic containment to be explored as an interim measure	Six months to one year
Remediation/containment plan to be developed and implemented	Two to three years
CHARACTERISATION AND REMEDIATION OF WASTE DUMPED IN LANDFILL IN THE SEP AREA	ONE TO TWO YEARS
Characterisation of waste and development of a basket of disposal/decontamination/remediation options	One year
Disposal/remediation of the waste and decontamination of the landfill area	One to two years
REMEDiation OF ENTIRE SEP AREA	THREE TO FIVE YEARS
Assessment of the need of geohydrological and contamination analysis based on previous reports	Three months
If required, SEP to be studied for waste characterisation and source of groundwater contamination	One year
Development and implementation of the remediation plan keeping residential purpose in mind	Three to five years
DETOXIFICATION, DISMANTLING AND DECOMMISSIONING OF UCIL PLANT, MACHINERY AND STRUCTURE	TWO YEARS
MIC plant including the vent, vent scrubber, storage tanks and control room to be strengthened and preserved	Two years
Remaining parts of the site to be decontaminated, dismantled and decommissioned as recommended by IICIT	Two years
REMEDiation AND FATE OF THE UCIL SITE	THREE TO FIVE YEARS
Geohydrological and contamination studies for the site based on stratified judgmental sampling	Two years
Development of a basket of decontamination/disposal methods accordingly	Two to three years
Remediation plan based on future use as a memorial and a centre of excellence	Two to three years
An international competition on master planning for conversion of the site	One year
Implementation of the remediation plan and conversion of the site to a memorial and a centre of excellence	Three to five years

No progress on 2013 plan



Videos taken August 2023
©thechemicaldetective
www.thechemicaldetective.com

Bhopal Gas Tragedy

02/03 December 1984
Bhopal, Madhya Pradesh, India

UNION CARBIDE

02 December
9.30 p.m.

10.30 p.m.
• Water escapes into main process pipe system, and essentially MIC storage tank E-610.
• Chemical reaction between MIC and water begins.

11.00 p.m.
• MIC storage tank pressure rises to 1.7 bar, which is still within safe operating limits of 1.1 bar to 2.7 bar..

03 December
12.15 a.m.

• MIC storage tank pressure rises rapidly from 3.1 bar to 4.8 bar.
• Operator senses heat radiating and rumbling noises from tank.
• Supervisor starts Vent Gas Scrubber (VGS) circulation pumps.

12.25 a.m.

• Chemical reaction between MIC and water becomes uncontrolled..
• MIC gas starts escaping from VGS stack.

12.45 a.m.

Education of Workers

Shortest training: 8 weeks
Underqualified Methyl isocyanide (MIC) operators
Plant operating manual is only available in English

Green Revolution

Keen on establishing chemical industry
Lacks enforceable international standards for environmental safety and industrial disaster preparedness.

False Information

1 Residents of adjacent bastis
"Plant is making 'sawdust' for export"
"MIC is a harmless high yield fertilizer"

Staffing Policy

Operates continued to plant despite severe 9 months, but never the trouble of reuse examinations
Demand for extra safety precautions led to warnings that appointments could be terminated
Workers and operators routinely exposed to toxic chemicals

City & State Authorities

Not provided with information on the chemicals in plants
Evaluation plan
Emergency response system
Medical plan
Lack of
Company policy forbade employees to speak for the company without authorization, especially in emergency situation

Union Carbide India Limited

UCIL Cost Cutting Measures

Positions of Maintenance Supervisor, Operating Shifts, Maintenance Shifts

casual workers

New hires came under training period were treated as casual workers
Workers and operators routinely exposed to toxic chemicals
Methyl isocyanide (MIC)
Carbon tetrachloride
Trichloro ethylene
Acetylene
Catalytic Dust

Early Warnings

1974 Residents found a well contaminated. Analyses of soil showed contamination with heavy metals.
1976 Two trade unions reacted to plant pollution issue. Letters went to plant manager, factory inspector, and Ministry of Labour of Madhya Pradesh.
1978 Factory caught in a big fire. Flammable materials were caught starting in cylinders other than those designated for purpose.
1981 Worker splashed with propane and died after 72 hours.
1982 January Propane tank February, August, October MIC leak (resulting in burns over body of victim)
1983-1984 "Highlighting regularly leaks of MIC, chlorine, phosgene, isocyanide, phosgene, and carbon tetrachloride."

Bhopal Disaster

December 3, 1984
• 0 trained engineer on site.
• 3000 - 10000 died during the first week.
• 100000 - 200000 have got permanent damage.
520000+ exposed to the gases
200000+ were children

Largest Chemical Industry Accident

Content of Gas Cloud

Union Carbide has not released the information they have available.
Possible Components
Methyl isocyanide
Methanethiocarbonyl
Hydrogen cyanide
Carbon monoxide
Carbon dioxide
Nitrogen oxides
Sulfur dioxide
Chloroform
Hydrogen chloride
Phosgene
Leading to Hypoxia and Asphyxia

Health Effect

Effects
Ophthalmic
Respiratory
Immunological
Neurological
Neuro-muscular
Cancers
Gynecological
Including sterility and miscarriages
Short term
Long term

State of Safety System

on December 3, 1984
Under consideration of safety measures
Insufficient maintenance

MINIMISE

Use small quantities of hazardous substances
Reduction of MIC intermediate inventory
MIC is not essential as a raw material nor a product.

HAZARD ASSESSMENT NOT HIGHLIGHTED BY:

1. UCIL
2. LOCAL AUTHORITY
Feasibility and safety levels of UCIL plant not evaluated
Allocation of UCIL plant close to densely populated settlements Due to economic advantages
Unrestricted large scale manufacturing and storage of pesticide

UCIL FAILED TO DELIVER AN EFFECTIVE ERP.

During leakage After leakage
Three main components:
Prevention
Internal and external communication
Mitigation

EMPLOYEE PARTICIPATION

Regular Training and Performance Assessment of Employees
Period of safety training was reduced from 6 months to 15 days
Neglect of specific instructions
• Failure to communicate
Giving orders without comprehending the nature of task
• Not taking efficient corrective measures
Poor perception of risks severity
• Manpower in safety and maintenance was reduced to save cost.

INHERENTLY SAFER DESIGN REPLACE SOURCE OF HAZARD

Replace hazardous reaction with one of less hazard
SUBSTITUTE
Use a safer process route. Avoid MIC formation. React alpha-naphthol and phosgene to produce chloroformate ester, followed by reaction with methylamine to yield carbaryl

SIMPLIFY

Eliminate unnecessary complexity to reduce risk of human error
Design equipment to totally contain MIC at ambient temperature or the maximum attainable process temperature.

UNDER-DIMENSIONING OF SAFETY FEATURES

Vent gas scrubber could not handle the large influx of MIC even if it were in operation.

REDUCED EMPHASIS ON SAFETY

INSUFFICIENT MAINTENANCE
Concentration of chloroform in the tank was too high.
The tank was not pressurised due to a leaky valve.
The tank's high-temperature alarm was not functioning.
Flare tower was disconnected from the plant pipe system.
Many valves, vent lines, feed lines, etc. were in poor condition.

ASSET INTEGRITY AND RELIABILITY

1 The refrigeration system was not in use.
2 Tank temperature was not logged.
3 Operator thought the tank's pressure meter was unreliable.
4 Evacuation tank E-619 was not empty.
5 Corroding iron pipelines were used.
6 Vent gas scrubber was under maintenance.
7 Water curtains were not tall enough to mitigate the gas leak.

BHOPAL GAS TRAGEDY


2 - 3 December 1984
Bhopal, Madhya Pradesh, India.

IChemE ADVANCING CHEMICAL ENGINEERING WORLDWIDE



Loss Prevention Bulletin

Improving process safety by sharing experience



IChemE

References

Loss Prevention Bulletin – 30 Years on

https://www.icheme.org/media/1277/lpb240_digimag.pdf

*Plan Environmental Remediation in and around
Action Plan CSE India Environmental Remediation
Environment, India*
http://cseindia.org/userfiles/Action%20Plan_Environmental%20Remediation%20in%20and%20around%20UCIL,%20Bhopal.pdf

SEISO Medal – winning student entry
SEISO Medal winning student entry poster

<https://www.icheme.org/media/12445/tzelin-sieso-medal-2019-graphic-art-1.jpg>


<https://www.icheme.org/media/12446/tzelin-sieso-medal-2019-graphic-art-2.jpg>

Rethinking Bhopal by Kenneth Bloch

<https://shop.elsevier.com/books/rethinking-bhopal/bloch/978-0-12-803778-2>

Long-term health and human capital effects of in utero exposure to an industrial disaster: a spatial difference-in-differences analysis of the Bhopal gas tragedy Gordon C McCord BMJ Open

<https://bmjopen.bmj.com/content/13/6/e066733>



Appendix

Root Cause Analysis

Equipment reliability

Transfer pumps
unreliable

Operational change
approved to bypass
the MIC pumps

Pumped transfer
was changed to
pressure transfer

Nitrogen was
diverted to
pressurise the tank

Circulation pumps
unreliable

In line quality
sampling stopped

MIC Refrigeration
stopped

High Temperature
alarms overridden
High pressure
ignored

Materials of Construction

Vent header constructed in carbon steel instead of stainless steel

Dry Nitrogen was required to prevent corrosion

However

Nitrogen diverted to provide MIC pressure transfer

Vent header began to corrode

Iron catalysed reactions formed solids (trimer) in the vent header

Backpressure affected the quality of distillate

The vent header was routinely washed with water to remove the solids

Process Hazard Analysis

Phosgene gas risks understood and controlled

Phosgene gas made in-situ and consumed

Original US process involved an intermediate that boiled at 296C

However

Revised US process used MIC with boiling point of 35C

MIC forms solid trimers with iron

MIC reacts violently with water

Dry Inert and Rust-free Conditions Essential

Vent gas scrubber not operating.
Vent gas flare disconnected and unavailable

Jumper added to connect (Emergency) Relief Vent and Process Vent Headers

Level 80% (design upper limit 60%)

Temperature out of range and in permanent state of alarm ((11°C)

Misguided attempt to clean vent valve by washing with water relying on a single isolation (common valve)

No working pumps available
No refrigeration or sampling available

